



Certificate CA96/157.00

The management system of

The PIC Group Limited

111 Simcoe St. N., 2nd Floor
Oshawa, ON L1G 4S4, Canada

has been assessed and certified as meeting the requirements of

ISO 9001:2015

For the following activities:

The design, development and provisions for training programs, and materials for quality related public seminars and in-house training courses. The provisions for quality related inspection, engineering, consulting and training resource services.

Further clarifications regarding the scope of this certificate and the applicability of ISO 9001:2015 requirements may be obtained by consulting the organization.

This certificate is valid from 30 August 2015 until 30 August 2018 and remains valid subject to satisfactory surveillance audits. Recertification audit due a minimum of 60 days before the expiration date. Issue 7: 7 July 2017. Certified since January 1996.

The audit leading to this certificate commenced on 11/05/2017. Previous issue certificate validity date was until 30/08/2018.


This is a multi-site certification. Additional site details are listed on subsequent pages.

Authorized by:

Ralph McLouth
Vice President of Accreditation, North America
SGS North America, Inc.
201 Route 17 North, Rutherford, NJ 07070, USA
t (201) 508-3000 f (201) 935-4555 www.us.sgs.com

This certificate remains the property of SGS and shall be returned upon request

Page 1 of 2



Certificate CA96/157.00, continued



The PIC Group Limited

ISO 9001:2015

Issue 7: 7 July 2017



Additional facilities:

202 South Blair St., Whitby, ON L1N 8X9, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

104 Dawson Road, Guelph, ON N1H 1A7, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

200 Universal Road, Unit 1, Woodstock, ON N4S 7W3, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

1303 McDougall Avenue, Windsor, ON N8X 3M6, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

QUALITY SOLUTIONS, S.A. DE C.V. , Av. Sierra Leona No. 360, PISO #9 Fraccionamiento Villa Antigua, San Luis Potosi, S. L. P., 78214, Mexico

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

The PIC Group Inc., 50459 Central Industrial Drive

Shelby Township, MI 48315, United States

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

